

Oil Field Environmental Incident Summary

Incident: 20150409102052 **Date/Time of Notice:** 04/09/2015 10:20

Responsible Party: PETRO-HUNT, L.L.C.

Well Operator: PETRO-HUNT, L.L.C.

Well Name: BLIKRE 158-93-6A-7-1H

Field Name: EAST TIOGA

Well File #: 22738

Date Incident: 4/9/2015

Time Incident: 08:15

Facility ID Number:

County: MOUNTRAIL

Twp: 158

Rng: 93

Sec: 6

Qtr:

Location Description:

Submitted By: Derek Enderud

Received By:

Contact Person: Derek Enderud
PO BOX 935
BISMARCK, ND 58502

General Land Use: Pasture

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Vessel Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units
Oil	15	Barrels

Recovered	Units

Followup	Units
15	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 4/21/2015

Clean Up Concluded: 4/15/2015

Risk Evaluation:

none

Areal Extent:

Potential Environmental Impacts:

potential impacts to vegetation.

Action Taken or Planned:

Vac truck is en route to cleanup oil on location. Will wait to hear from NDIC & Landowner on recommended cleanup off location. Left a voicemail for John Axtmann at 08:58 MDT.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 4/9/2015 **Status:** Reviewed - Follow-up Required

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release from vessel leak impacted area off location. Followup is required.

Date: 4/22/2015 **Status:** Inspection

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

4/22/2015 at 17:49, on location. Stained and burnt vegetation off east side of wellpad into pasture, directly east of heater treater. Staining also visible on wellpad. Email sent to report contact to inquire about cleanup plans.

Date: 4/30/2015 **Status:** Correspondence

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Email conversation with report contact. Fire was applied as part of the remediation plan as landowner did not want topsoil disturbed. Notified report contact that NDDoH requires such burns to apply for prior approval to burn hydrocarbons. Report contact has informed staff of the matter. Also requested a letter between the responsible party and the landowner since the landowner does not want the impacted vegetation removed.

Date: 10/6/2015 **Status:** No Further Action Requested

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Received burn permit and signed landowner authorization from Petro-Hunt. They can be found in the report folder. No further action required at this time.